



smell. leave. tell.

HOW TO recognize a gas leak:

SMELL IT.

Natural gas is colorless and odorless. A distinctive, pungent odor, similar to rotten eggs, is added for quick recognition.

SEE IT.

You may see a white cloud, mist, fog, bubbles in standing water or blowing dust. You may also see vegetation that appears to be dead or dying for no apparent reason.

HEAR IT.

You may hear unusual noises like roaring, hissing or whistling.

continued on back



smell. leave. tell.

IF YOU detect a gas leak:

Leave the area immediately and move to a safe environment.

Call 911 immediately or Eversource at **877-944-5325**.

Do not smoke or operate electrical switches, appliances, cell phones and land lines. These items may produce a spark that can ignite the gas and cause an explosion.

Do not assume someone else will report the condition.

Provide the exact location, including cross streets.

Let us know if digging activities are going on in the area.

EVERSOURCE

Working Together
To Be Safe.